

Test report

T-24235530-10-R2



Verify Report

Overall result

Pass

Please refer to the following pages for test result summary and notes.

Client information

Client: Star-Tags Textilimport Und Merchandising
GmbH
Address: Frei-Otto-Strasse 6 80797 Muenchen



Sample information

Description: 3132402610 Audi Cap weiss/white
3132402620 Audi Cap rot/red
3132402630 Audi Cap schwarz/black
3131402640 Audi Cap grau/grey

SKU/style #: 3132402610 3132402620 3132402630 3131402640

Country of origin: -

Purchase order #: 2024-312596

Country of distribution: -

Labeled age grade: -

Color: white/red/black/grey

Requested age grade: Adult

Composition: Shell: 65%Polyester 35% Cotton

Tested age grade: -

Lining: 65%Polyester 35% Cotton

Buyer: AUDI

Age group: Adult

Quantity submitted: 6 pcs per style + a lot parts

General information

Sample receipt date: 09-Oct-2024

Report date: 30-Oct-2024

Testing period: 10-Oct-2024 to 22-Oct-2024

QIMA (Hangzhou) Testing Co., Ltd.

Carina Zhou

Textile Laboratory Manager



Verify Report



QIMA (Hangzhou) Testing Co., Ltd.
Room 401 4-5/F, Building 1, No.1213 Huoju South Road,
Puyan Subdistrict, Binjiang District, Hangzhou, China



Result summary

At the request of the client, the following test were conducted:

Test(s) conducted	Conclusion
SOR/2016-194-Textile Flammability Regulations-Non-bedding Textile	Pass



Verify Report





Detailed results

SOR/2016-194-Textile Flammability Regulations-Non-bedding Textile

Test Method: CAN/CGSB-4.2 No.27.5-2023

Specimen No.	22-Shell			
Preliminary Tests	<u>Fabric Surface</u>	Smooth	<u>Test Specimen Direction</u>	Face Length
Items	Result			
	<u>As Received</u>		<u>After Dry-cleaning and Laundering*</u>	
	<u>Flame Spread (sec.)</u>	<u>Burn Code</u>	<u>Flame Spread (sec.)</u>	<u>Burn Code</u>
(1)	-	-	-	DNI
(2)	-	-	-	DNI
(3)	-	-	-	DNI
(4)	-	-	-	DNI
(5)	-	-	-	DNI
Conclusion	Pass			

* Dry-cleaning / Laundering procedure is according to Commercial Dry Cleaning / CAN/CGSB-4.2 No.58-2019, Procedure 5, Dry Procedure D1; Moderate mechanical action at 50°C, Synthetic detergent, Tumble dry normal.

Burn Code Description:

DNI = Did not ignite;



Verify Report



QIMA (Hangzhou) Testing Co., Ltd.
Room 401 4-5/F, Building 1, No.1213 Huoju South Road,
Puyao Subdistrict, Binjiang District, Hangzhou, China



Detailed results

SOR/2016-194-Textile Flammability Regulations-Non-bedding Textile

Test Method: CAN/CGSB-4.2 No.27.5-2023

Specimen No.	23-Shell			
Preliminary Tests	<u>Fabric Surface</u>	Smooth	<u>Test Specimen Direction</u>	Face Length
Items	Result			
	<u>As Received</u>		<u>After Dry-cleaning and Laundering*</u>	
	<u>Flame Spread (sec.)</u>	<u>Burn Code</u>	<u>Flame Spread (sec.)</u>	<u>Burn Code</u>
(1)	-	-	-	DNI
(2)	-	-	-	DNI
(3)	-	-	-	DNI
(4)	-	-	-	DNI
(5)	-	-	-	DNI
Conclusion	Pass			

* Dry-cleaning / Laundering procedure is according to Commercial Dry Cleaning / CAN/CGSB-4.2 No.58-2019, Procedure 5, Dry Procedure D1; Moderate mechanical action at 50°C, Synthetic detergent, Tumble dry normal.

Burn Code Description:

DNI = Did not ignite;



Verify Report



QIMA (Hangzhou) Testing Co., Ltd.
Room 401 4-5/F, Building 1, No.1213 Huoju South Road,
Puyao Subdistrict, Binjiang District, Hangzhou, China



Detailed results

SOR/2016-194-Textile Flammability Regulations-Non-bedding Textile

Test Method: CAN/CGSB-4.2 No.27.5-2023

Specimen No.	24-Shell			
Preliminary Tests	<u>Fabric Surface</u>	Smooth	<u>Test Specimen Direction</u>	Face Length
Items	Result			
	<u>As Received</u>		<u>After Dry-cleaning and Laundering*</u>	
	<u>Flame Spread (sec.)</u>	<u>Burn Code</u>	<u>Flame Spread (sec.)</u>	<u>Burn Code</u>
(1)	-	-	-	DNI
(2)	-	-	-	DNI
(3)	-	-	-	DNI
(4)	-	-	-	DNI
(5)	-	-	-	DNI
Conclusion	Pass			

* Dry-cleaning / Laundering procedure is according to Commercial Dry Cleaning / CAN/CGSB-4.2 No.58-2019, Procedure 5, Dry Procedure D1; Moderate mechanical action at 50°C, Synthetic detergent, Tumble dry normal.

Burn Code Description:

DNI = Did not ignite;



Verify Report



QIMA (Hangzhou) Testing Co., Ltd.
Room 401 4-5/F, Building 1, No.1213 Huoju South Road,
Puyan Subdistrict, Binjiang District, Hangzhou, China



Detailed results

SOR/2016-194-Textile Flammability Regulations-Non-bedding Textile

Test Method: CAN/CGSB-4.2 No.27.5-2023

Specimen No.	25-Shell			
Preliminary Tests	<u>Fabric Surface</u>	Smooth	<u>Test Specimen Direction</u>	Face Length
Items	Result			
	<u>As Received</u>		<u>After Dry-cleaning and Laundering*</u>	
	<u>Flame Spread (sec.)</u>	<u>Burn Code</u>	<u>Flame Spread (sec.)</u>	<u>Burn Code</u>
(1)	-	-	-	DNI
(2)	-	-	-	DNI
(3)	-	-	-	DNI
(4)	-	-	-	DNI
(5)	-	-	-	DNI
Conclusion	Pass			

* Dry-cleaning / Laundering procedure is according to Commercial Dry Cleaning / CAN/CGSB-4.2 No.58-2019, Procedure 5, Dry Procedure D1; Moderate mechanical action at 50°C, Synthetic detergent, Tumble dry normal.

Burn Code Description:

DNI = Did not ignite;



Verify Report



QIMA (Hangzhou) Testing Co., Ltd.
Room 401 4-5/F, Building 1, No.1213 Huoju South Road,
Puyan Subdistrict, Binjiang District, Hangzhou, China



Specimen description

Specimen #	Specimen description	Location
22	Black cap	Finished product
23	Red cap	Finished product
24	White cap	Finished product
25	Grey cap	Finished product




Verify Report





Pictures

Sample photo:



End of the report

The test result(s) and conclusion(s) in this report relate only to the sample(s) as received and the method /regulation section(s) tested as described herein. If it is not further specified in the report, the decision rule for stating conformity is based on the QIMA decision rule. (<https://www.qima.com/conditions-of-service#decisionRule>). This test report may not be reproduced in whole or in part, without the written approval of QIMA (Hangzhou) Testing Co., Ltd.



Verify Report



QIMA (Hangzhou) Testing Co., Ltd.
Room 401 4-5/F, Building 1, No.1213 Huoju South Road,
Puyan Subdistrict, Binjiang District, Hangzhou, China

support@qima.com • ©QIMA Limited
Page 8 of 8